

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

FIREBOAT JOHN J. HARVEY
Pier 63, North River
New York
New York County
New York

HAER NY-335

Photos 1-9 taken while in dry dock at Direktor Shipyard in Bridgeport, CT on June 14, 2005

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Gerald Weinstein, photographer, December 2005

NY-335-1	ELEVATION OF PORT SIDE STRAIGHT ON IN SHIPYARD.
NY-335-2	3/4 VIEW OF PORT SIDE ELEVATION LOOKING AFT. FIREFIGHTING EQUIPMENT CAN BE SEEN ON DECK. WATER INTAKE PORTS ARE LOCATED AMIDSHIP UNDER THE WATERLINE.
NY-335-3	3/4 VIEW OF PORT SIDE ELEVATION LOOKING FORWARD. FIREFIGHTING EQUIPMENT CAN BE SEEN ON DECK AND PROPS AND RUDDER UNDER THE WATERLINE.
NY-335-4	BOW ELEVATION, LOOKING AFT.
NY-335-5	STERN ELEVATION, LOOKING FORWARD. PROPS AND NAMEPLATE IN VIEW.
NY-335-6	DETAIL OF HULL CONSTRUCTION AT BOW SHOWING IRON PLATES AND RIVETS AT STEM AND KEEL.
NY-335-7	DETAIL OF PROPS, SHAFT AND RUDDER. SACRIFICIAL ZINCS ARE ATTACHED TO PREVENT CORROSION OF METAL PARTS.

FIREBOAT JOHN J. HARVEY

HAER NY-335

INDEX TO PHOTOGRAPHS

(Page 2)

NY-335-8 DETAIL OF WATER INTAKES FOR FIREFIGHTING SYSTEM
ON STARBOARD SIDE OF BOAT UNDER THE WATERLINE.
ZINCS ARE ALSO ADDED HERE TO PRESERVE THE
METAL.

NY-335-9 DETAIL OF WATER INTAKE PORT.